From: <u>Vincent Malott</u>
To: <u>Nancy Johnson</u>

Subject: RE: Update on Circle Court Drum Assessment

Date: 08/03/2012 01:13 PM

Thanks Nancy. I called and left a message on Devon's voicemail system.

Vincent Malott, P.G. Remedial Project Manager EPA Region 6 - Superfund (6SF-RA) 214-665-8313 malott.vincent@epa.gov

■ Nancy Johnson ---08/03/2012 11:31:11 AM---That would be Devon Energy.

Attached is some info to help you reference the pad site. From: Vincent

From: Nancy Johnson < nancy.johnson@tceq.texas.gov>

To: Vincent Malott/R6/USEPA/US@EPA

Date: 08/03/2012 11:31 AM

Subject: RE: Update on Circle Court Drum Assessment

That would be Devon Energy. Attached is some info to help you reference the pad site.

From: Vincent Malott [mailto:Malott.Vincent@epamail.epa.gov]

Sent: Friday, August 03, 2012 9:04 AM

To: Nancy Johnson

Subject: RE: Update on Circle Court Drum Assessment

Nancy,

I called and left messages for Mr Gaby and Mr. Johnson.

By the way, do you recall the name of the operator for the gas well on Russell Road? I wanted to call and give them a heads-up on the Thursday meeting. Thanks.

Vincent Malott, P.G.
Remedial Project Manager
EPA Region 6 - Superfund (6SF-RA)
214-665-8313
malott.vincent@epa.gov

From: Nancy Johnson < nancy.johnson@tceq.texas.gov >

To: Vincent Malott/R6/USEPA/US@EPA

Date: 08/03/2012 08:58 AM

Subject: RE: Update on Circle Court Drum Assessment

That's good news. Have you advised Mr. Gaby of the results, or would you like for me to contact him?

Thanks.
Nancy

From: Vincent Malott [mailto:Malott.Vincent@epamail.epa.gov]

Sent: Friday, August 03, 2012 8:46 AM **To:** Nancy Johnson; Bradford, Carrie (DSHS)

Subject: Update on Circle Court Drum Assessment

We received the waste characterization results for the liquid waste in the drum located on Russell Road and the only VOC detected was TCE at 0.274 mg/L. The drum contents are considered non-hazardous and may be shipped for off-site disposal the week of August 6th. While this was a TCLP analysis using 8260B, the results are comparable to a total VOC analysis and at least confirms that a TCE liquid or residue was present in the drum. Please let me know if you have any questions. Thanks.

Vincent Malott, P.G. Remedial Project Manager EPA Region 6 - Superfund (6SF-RA) 214-665-8313

malott.vincent@epa.gov [attachment "Russell Road gas pad.pdf" deleted by Vincent Malott/R6/USEPA/US]